Insurance Patrol Building 509 Arch Street Philadelphia Philadelphia County Pennsylvania

HABS PA 51-PHILA,

PHOTOGRAPH

HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE



DATE

ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY	
PENNSYLVANIA	PHILADELPHIA		PHILADELPHIA	
HISTORIC NAME OF STRUCTURE (INC.		NAME)	`	HABS NO.
INSURANCE PATROL BUILDING				PA-1433
SECONDARY OR COMMON NAMES OF STRUCTURE				
COMPLETE ADDRESS (DESCRIBE LOCA	ATION FOR RURAL	SITES)		
 509 Arch Street				
DATE OF CONSTRUCTION (INCLUDE S	OURCE)	ARCHITECT(S) (INC.	LUDE SOURCE)	
Probably 1879				
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)				
The building housed the insur	ance patrol, wh	nose function was	not to fight.	fires but rather
to save property. The activity was made possible by the insurance companies of the city. The patrol wagon was used to transport members of the patrol to fires. (con't. on page 2)				
	sport members o	of the patrol to	fires. (con't.	on page 2)
STYLE (IF APPROPRIATE)				
MATERIAL OF CONSTRUCTION (INCLUOE STRUCTURAL SYSTEMS)				
Brick with cast-iron front.			•	
SHAPE AND DIMENSIONS OF STRUCTU	JRE <i>(SKETCHEO F L</i>	OOR PLANS ON SEPAI	RATE PAGES ARE A	ACCEPTABLE)
Two-story building. Dimension	s: 27' X 205'.			•
EXTERIOR FEATURES OF NOTE				
The first floor of the front	facade was supp	ported by four ca	ast-iron column	is with recessed
panels and simple bases and capitals. On the corners of the second story portion of the fron facade were large decorative quoins. The building, which was three bays wide, (con't. on p. 2				
- 1		· · · · · · · · · · · · · · · · · · · 		ide,(con't. on p. 2
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)				
Not available. (The building was demolished after this report was written).				
MAJOR ALTERATIONS AND ADDITIONS WITH DATES				
At some later date, the large double doors were replaced with a plate glass window and the				
building was used for commerc.	ial purposes.		on a prace gran	's wringow dud oue
PRESENT CONDITION AND USE				
OTHER INFORMATION AS APPROPRIA	TE	<u> </u>		
There is a photocopy of an old	d photograph sh	owing the front	facade of the	huilding: natrol
There is a photocopy of an old photograph showing the front facade of the building, patrol crew and wagon, in a field record folder filed under this building.				
SOURCES OF INFORMATION (INCLUDI	ING LISTING ON NA	TIONAL REGISTER, S	TATE REGISTERS.	ETC.)
webster, Richard. Philadelphia Preserved. Philadelphia: Temple University, 1976.				
If the property of the first of the control of the				

COMPILER, AFFILIATION
From August 13, 1964 report by John G. Waite, NPS architect; edited by Susan McCown, Historic American Buildings Survey, April 11, 1984

SIGNIFICANCE (continued from page 1):

It also carried salvage covers which the crew used to protect property from water and smoke damage. The patrol would also patch up the roof and walls to protect property from weather damage and then would stand guard over a gutted building to prevent looting. The building was demolished in 1964 to make way for the Independence National Historical Park. (This report was written after the demolition).

EXTERIOR FEATURES OF NOTE (continued from page 1):

originally had a large arched double doorway in the center bay for the apparatus. On either side of the apparatus doorway was a smaller double doorway, with a semi-circular arch. All of the doorway arches contained decorative keystones. The original doors were probably of wood and paneled. All of the doorways were quite tall, being perhaps 10'-12' high, and gave the effect of being heavy. The double windows in the center bay of the second floor, front facade had semi-circular arched openings with decorative keystones. The single windows in the outside bays had segemental arched openings also with decorative keystones. The sash was 2/2 with slotted wood interior shutters. The jambs of the windows were decorated with a long straight stalk with an end spiral at the sill level. Over the first floor portion of the front facade was a rather heavy cornice supported by four large brackets between which were large modilions. At the top of the building was another heavy cornice, again supported by large brackets. Between the brackets was a scalloped treatment. The center uppermost part of the cornice originally consisted of a large segmental arched panel with the name "Insurance Patrol" displayed in raised letters. Over the panel was a rather delicate crest-like decoration.